



Noise Level Survey - Background noise levels at 70dB in block C & A3 in rooms adjacent to road

Soil Investigation - Highly shrinkable clay low load bearing capacity

**SAMPLE**